

Water Treatment on July 10, 2013


On July 10, 2013 PLM Lake and Land Management Corp. tested the water quality of Cedar Lake. All in all the lake was found to be in good condition. Samples were taken to test for e.coli. The lake was also spot treated for Eurasian Milfoil with the chemical Diquat Dibromide. The following restrictions apply for this chemical in the treated areas:

Chemical product/active ingredient	Chemical trade name	Do Not Use this water for swimming or bathing until	Do Not Use this water for ornamentals or turf irrigation until	Do Not Use this water for domestic purposes or agriculture irrigation until	Do Not Use this water for livestock watering or similar purposes until
Diquat Dibromide	Tribune	1 Day(s)	3 Day(s)	5 Day(s)	1 Day(s)

For a complete listing of all product labels, please see the [PLM website](#). The chemicals used for Aquatic Nuisance Control are registered by the U.S. Environmental Protection Agency and the Michigan Department of Agriculture. The potential for damage to fish and other non-target organisms is minimal provided that the product is used as directed on the product label and the permit. To minimize the possible effects on health and the environment, the treated water is restricted for the above purposes.

The areas of the lake that were treated are shown on the map below:

■ Eurasian Milfoil Treatment Areas



Cedar Lake
269 Surface Acres
VanBuren Cauty Porter Township
T4S, R13W, Sect 27,28,33
<small>Professional Lake Management, P.O. Box 132, Caledonia, MI 49316 Phone (800) 382-4434</small>